

Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

May 11, 1983

#7075487

REGISTERED RETURN RECEIPT REQUESTED

Mr. Tom Robison, General Manager Western Clay Company P. O. Box 1064 Aurora, Utah 84620

RE: Topsoil Handling

Redmond Limestone Quarry

ACT/041/004

Sevier County, Utah

Dear Mr. Robison:

As you will recall, on May 5, Division technical staff members visited the above-mentioned minesite for the purpose of viewing the test plot location and performing a cursory inspection.

At that time, it was apparent that topsoil handling procedures were not in accord with the Mining and Reclamation Plan (MRP). Of specific interest was the practice of blading soil off development areas followed by inadvertently pushing overburden over the topsoil. Once bladed off, topsoil should be stockpiled, the top of the stockpile should be flattened and seeding should follow as soon as possible.

Please refrain from this practice in the future. Every effort should be made to remove topsoil from overburden piles and segregate it for reclamation prior to June 1, 1983 in order to become in compliance with the Utah Mined Land Reclamation Act of 1975, Title 40-8 and the terms and conditions of your MRP. Failure on your part to achieve compliance in this matter may result in action before the Board of Oil, Gas and Mining.

If you have any questions, please don't hesitate to call.

Sincerely, Tham I than

THOMAS L. PORTLE

RECLAMATION SOILS SPECIALIST

TLP/btb

cc: John Blake, Division of State Lands and Forestry

J. Smith, DOGM

D. Wayne Hedberg, DOGM

S. Linner, DOGM